


- Notes:
1. This drawing is the property of ACP (Concrete) Ltd and is not to be copied in any way without prior written approval from AXP (Concrete) Ltd.
  2. Brackets A to be clipped to steel work using M12 bolts into cast in sockets. 4 No Brackets per panel (1 in each corner).
  3. Fixing Angles have two fixing scenarios:
    - a. Fix to prestressed concrete panels using M12 excalibar bolts or equivalent to the manufacturers specification.
    - b. Fix to steel column/beams using M12 bolts c/w nut & washer.

It is the responsibility of the main contractor to notify ACP(Concrete)Ltd of any subsequent revisions which may affect this design.

Rev.		Dwn	Date
	Checked By		


**ACP (Concrete) Ltd**  
 Wood Lane Business Centre  
 Wood Lane  
 Uttoxeter  
 Staffs  
 ST14 8JR  
 Tel:01889 598660 Fax:01889 568160

**Job Title:**  
 TYPICAL FIXING ARRANGEMENT  
 TO FACE OF COLUMNS & INSIDE  
 COLUMN WEBB